

35th Annual CES Facility Managers Training Workshop Program Schedule

Albuquerque Embassy Suites 1000 Woodward PI NE, Alb. 87102

GET THE knowLEDGE

Monday, October 18, 2021					
7:00am Registration– Pick up Materials					
Breakout Sessions	Sierra I	Sierra II	Sierra III	Ocotillo I	Agave
8:00 am-11:30pm	OSHA 10	Playground Safety	Roof Inspection	HVAC	Module 2 *
10:15am-11:30am	NMPFMA/Executive Committee			Pinon	
11:45am-1:15pm	Ben Lujan Awards Luncheon Ceremony			Atrium	
1:30pm-3:00pm	Master Cert Graduation and General Session Randy Rush: "What it Takes to be a Great Team Player"			Sierra Ballroom II,III	
3:00pm-3:30 pm	BREAK - Visit with Procurement Partners			Sandia Ballroom	
3:00pm-5:00pm	OSHA 10 Continued			Sierra I	
3:30pm-5:00pm	General Session Continued			Sierra Ballroom II,III	
5:00pm-7:00pm	Procurement Partner Welcome Social & Multiple Drawings			Sandia Ballroom	
Tuesday, October 19, 2021 - Registration opens at 7:00am					
7:00am-8:00am	Breakfast Buffet with Procurement Partners			Sandia Ballroom	
Breakout Sessions	Sierra I	Sierra II	Sierra III	Ocotillo I	Agave
8:00am - 9:30am	OSHA 10	Playground Safety	Roof Inspection	HVAC	Module 3 *
9:30am-10:00am	BREAK - Visit with Procurement Partners			Sandia Ballroom	
Breakout Sessions	Sierra I	Sierra II	Sierra III	Ocotillo I	Agave
10:00am-11:30am	OSHA 10	Playground Safety	Roof Inspection	HVAC	Module 3 *
12:00pm-1:15pm	Full Board Meeting Luncheon, Million Dollar Club Awards			Atrium	
12:00pm-1:15pm	Member and Procurement Partner Luncheon			Sandia Ballroom	
Breakout Sessions	Sierra I	Sierra II	Sierra III	Ocotillo I	Agave
1:15pm-2:45pm	OSHA 10	Fire Suppression	Turf Maintenance		Module 3 *
2:45pm-3:30pm	BREAK - Visit with Procurement Partners			Sandia Ballroom	
3:30pm-5:00pm	Ice Cream Social and drawings for Door Prizes			Sandia Ballroom	

35th Annual CES Facility Managers Training Workshop Program Schedule

Albuquerque Embassy Suites 1000 Woodward PI NE, Alb. 87102

GET THE knowLEDGE

Wednesday, October 20, 2021						
7:00am-8:00am		Breakfast Buffet			Sandia Ballroom	
Breakout Sessions	Sierra I	Sierra II	Sierra III	Ocotillo I	Agave	
8:00am-9:30am	Gym Floor Maintenance	How to protect the Building Envelope	Asbestos Reg Compliance	Fire Suppression		
9:30am-9:45am BREAK						
10:00am-11:00am		Round table discussion, Maintenance Concerns (Facility Managers Team Representatives)			Sierra Ballroom	
11:00am		Grand Prize Drawings			Sierra Ballroom	

The Playground Safety and Roof Inspection sessions will meet for classroom instruction then travel offsite.

HVAC Group will meet in Ocotillo I then travel to TLC for these sessions

OSHA 10 requires 10 hours of attendance; all hours must be attended to receive the OSHA 10 certificate. All OSHA 10 sessions will be held in Sierra I

* Denotes a certificate class